

Intel[®] 400 Series Chipset Family On- Package Platform Controller Hub (PCH)

Specification Update

Revision 008

November 2020



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration. No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Intel technologies may require enabled hardware, specific software, or services activation. Check with your system manufacturer or retailer.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.


All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or visit www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.


© Copyright 2019-2020 Intel Corporation. All rights reserved.



Contents

Preface	5
Summary Tables of Changes	6
Errata Summary Table	7
Errata	9
Specification Change	14
Specification Clarification	15

§ §



Revision History

Revision Number	Description	Release Date
001	<ul style="list-style-type: none">Initial Release	September 2019
002	<ul style="list-style-type: none">The following erratum is added:<ul style="list-style-type: none">xHCI Short Packet Event Using Non-Event Data TRB.For the steppings affected, refer to the Summary Tables of Changes.	November 2019
003	<ul style="list-style-type: none">Updated the following errata:<ul style="list-style-type: none">USB DbC or Device Mode Port When Resuming from S3, S4, S5, or G3 StateDbC (Debug Capability) Device Fails To Enumerate When Connected To USB 3.2 Gen 2x1 PortxHCI Power Management Link TimerAdded the following errata:<ul style="list-style-type: none">xHCI Host Controller Reset May Cause a System HangxHCI Protocol Speed ID Count Field	January 2020
004	<ul style="list-style-type: none">Added the following errata:<ul style="list-style-type: none">Intel® Serial I/O Controller DMA LLP 4 GB Boundary AlignmentSystem May Hang with USB-C* Power Adapter	April 2020
005	<ul style="list-style-type: none">Added the following specification clarification:<ul style="list-style-type: none">PCIe Precision Time Measurement (PTM) Byte Order	June 2020
006	<ul style="list-style-type: none">Added the following erratum:<ul style="list-style-type: none">Audio Global Time Synchronization Register Access	August 2020
007	<ul style="list-style-type: none">Added the following erratum:<ul style="list-style-type: none">Phase Lock Loop (PLL) Feedback Circuit	September 2020
008	<ul style="list-style-type: none">Added the following Specification Clarification:<ul style="list-style-type: none">SX_EXIT_HOLDOFF# Not Functional with eSPI Enabled	November 2020

§ §



Preface

This document is an update to the specifications contained in the Affected Documents table below. This document is a compilation of device and documentation errata and specification changes, specification changes and Specification clarifications. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

Affected Documents

Title	Document Number
Intel® 400 Series Chipset Family On-Package Platform Controller Hub (PCH) Datasheet	615170 (Vol1) 615146 (Vol2)

Nomenclature

Errata are design defects or errors. Errata may cause the behavior of the PCH to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present in all devices.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.





Summary Tables of Changes

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the product. Intel may fix some of the errata in a future stepping of the component and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

Codes Used in Summary Tables

Status

Doc:	Document change or update will be implemented.
Plan Fix:	This erratum may be fixed in a future stepping of the product.
Fixed:	This erratum has been previously fixed in Intel® hardware, firmware, or software.
No Fix:	There are no plans to fix this erratum.



Errata Summary Table

Erratum ID	Stepping	Errata
	A0	
1	No Fix	USB DbC or Device Mode Port When Resuming from S3, S4, S5, or G3 State
2	No Fix	xHCI Minor Revision Value
3	No Fix	xHCI Link Error Count Field
4	No Fix	xHCI U1 Exit LFPS Duration
5	No Fix	xHCI Power Management Link Timer
6	No Fix	DbC (Debug Capability) Device Fails To Enumerate When Connected To USB 3.2 Gen 2x1 Port
7	No Fix	eMMC*/SDXC CRC Detection
8	No Fix	Intel® Trace Hub Pipe Line Empty
9	No Fix	SPI SFDP Program Suspend and Program Resume Instruction Fields Not Used
10	No Fix	PCIe* Root Port CLKREQ# Asserted Low to Clock Active Timing
11	No Fix	xHCI USB 2.0 ISOCH Device Missed Service Interval
12	No Fix	xHCI Link Protocol Field Value
13	No Fix	xHCI Short Packet Event Using Non-Event Data TRB
14	No Fix	eSPI SBLCL Register Bit Not Cleared by PLTRST#
15	No Fix	xHCI Host Controller Reset May Cause a System Hang
16	No Fix	xHCI Protocol Speed ID Count Field
17	No Fix	Intel® Serial I/O Controller DMA LLP 4 GB Boundary Alignment
18	No Fix	System May Hang with USB-C* Power Adapter
19	No Fix	Audio Global Time Synchronization Register Access



Erratum ID	Stepping	Errata
	A0	
20	No Fix	Phase Lock Loop (PLL) Feedback Circuit


Specification Change

Number	Stepping	Specification Change
	A0	
		No specification changes in this revision of the Specification Update

Specification Clarification

Number	Specification Clarification
1	PCIe Precision Time Measurement (PTM) Byte Order
2	SX_EXIT_HOLDOFF# Not Functional with eSPI Enabled

§ §



Errata

1. USB DbC or Device Mode Port When Resuming from S3, S4, S5, or G3 State

Problem: If a PCH USB Type-C* port is configured in Device Mode (or in DbC mode) and connected to an external USB 3.2 host controller, it may cause the USB port to go into a non-functional state in the following scenarios:

1. The PCH resumes from S3, S4, or S5 state, the port may remain in U2.
2. The port is connected to a USB 3.2 Gen 1x1 host controller when resuming from S3, S4, S5 or G3, the port may enter into Compliance Mode or an inactive state if Compliance mode is disabled.
3. The port is connected to a USB 3.2 Gen 2x1 host controller when resuming from S3, S4, S5 or G3, the port may enter an inactive state.

Implication: PCH USB Type-C port configured in Device Mode (or in DbC mode) may fail to enumerate or become unavailable.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

2. xHCI Minor Revision Value

Problem: The PCH reports USB Minor Revision in the XECP_SUPP_USB3_0 register (offset 8020h) as 01h. The USB-IF released a ECN to update the minor revision to 10h.

Implication: USB-IF xHCI CV TD 1.5 may report a failure. Intel has obtained a waiver for TD 1.5.

Note: No functional impact is expected.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

3. xHCI Link Error Count Field

Problem: The xHCI Link Error Count Field in the USB 3.0 Port X Link Info – (PORTLI) register is implemented as Read/Write instead of Read Only as defined by the xHCI specification.

Implication: USB-IF xHCI CV TD 3.17 may report a failure. Intel has obtained a waiver for TD 3.17.

Note: No functional impact is expected.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

4. xHCI U1 Exit LFPS Duration

Problem: The xHCI U1 Exit LFPS (t13-t11) duration timing is implemented as 0.6 us to 0.9 us. The USB-IF released a ECN updating this timing value to 0.9 us to 1.2 us.

Implication: USB-IF xHCI CV TD 7.18 may report a failure. Intel has obtained a waiver for TD 7.18.

Note: No functional issues are expected.

Workaround: None identified.



Status: For the steppings affected, refer to the Summary Tables of Changes.

5. xHCI Power Management Link Timer

Problem: The xHCI implements the Power Management Link Timer (PM LC Timer) Timeout value as 10 us instead of 4 us as defined by the USB 3.2 specification.

Implication: USB-IF xHCI CV TD 7.21 may report a failure. Intel has obtained a waiver for TD 7.21.

Note: No functional issues are expected.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

6. DbC (Debug Capability) Device Fails To Enumerate When Connected To USB 3.2 Gen 2x1 Port

Problem: The PCH DbC (Debug Capability) Device may fail to enumerate if connected to a USB host controller's USB 3.2 Gen 2x1 port.

Implication: The PCH DbC may not function.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

7. eMMC*/SDXC CRC Detection

Problem: The eMMC or SDXC controllers may fail to detect a CRC error if a bit error occurs on the DATA3 signal during read operations when in eMMC DDR50/HS400 mode or SDXC DDR50 mode. CRC detection on other DATA signals is not impacted.

Implication: The controller will not flag the CRC error to the driver or application, which could result in data integrity issues. Bit errors on eMMC or SDXC DATA signals are not expected on platforms that follow Intel recommended design guidelines and tuning processes.

Workaround: None identified. To mitigate the issue, eMMC HS200 or SDXC SDR50 modes can be used instead of HS400 or DDR50.

Status: For the steppings affected, refer to the Summary Tables of Changes.

8. Intel® Trace Hub Pipe Line Empty

Problem: The Intel® Trace Hub Pipe Line Empty bit (CSR_MTB_BAR, Offset D4h) for a given output port may be set while the Input Buffer Empty for the associated output port is not set. This will only happen when the captureDone signal is de-asserted by clearing the ForceCaptureDone bit (CSR_MTB_BAR, Offset D8h) is cleared or the StoreQual[0] signal is de-asserted by the Trigger Unit before the pipe line is empty, and the destination is either system memory or USB (DCI).


Implication: There may be valid trace data in the trace source input buffer which did not get sent to the destination (output port).

Workaround: None identified. CaptureDone should be cleared or de-asserted after the pipe line is empty.

Status: For the steppings affected, refer to the Summary Tables of Changes.

9. SPI SFDP Program Suspend and Program Resume Instruction Fields Not Used

Problem: For flash device suspend / resume opcodes, the SPI controller does not use JEDEC SFDPs 13th DWORD bits [15:0], Program Suspend Instruction and Program Resume Instruction fields. The controller only uses bits [31:16], Suspend Instruction and Resume Instruction fields, to obtain the suspend / resume opcodes.



Implication: If the SPI flash requires bits [15:0] to be different than bits [31:16], then the suspend / resume feature is not functional. In this case, system behavior varies depending on what the suspend / resume instruction is and when it is generated.

Note: Major flash vendors have been using the same value for bits [31:16] and bits [15:0].

Workaround: None identified.
If a device requires bits [15:0] to be different than bits [31:16], then disable the device suspend / resume via the SPI Suspend / Resume Enable soft strap.

Status: For the steppings affected, refer to the Summary Tables of Changes.

10. PCIe* Root Port CLKREQ# Asserted Low to Clock Active Timing

Problem: During L1 exit, the PCH PCIe* Root Ports may exceed the CLKREQ# asserted low to clock active maximum specification due to PCH PCIe clock un-gate path delays.

Implication: PCIe end point device L1 exit instabilities may be observed.

Note: PCIe end point devices that message LTR latency greater than or equal to 1 μ s are not affected by this.

Workaround: None identified.

- Platforms not supporting S0ix with PCIe end point devices that do not support LTR may disable the associated PCH SRCCLKREQ# signal to keep the PCIe clock active during L1.
- Platforms supporting S0ix with PCIe end point devices that have LTR latencies less than 1 μ s may disable the associated PCH SRCCLKREQ# signal to keep the PCIe clock active during L1.

Status: For the steppings affected, refer to the Summary Tables of Changes.

11. xHCI USB 2.0 ISOCH Device Missed Service Interval

Problem: When the xHCI controller is stressed with concurrent traffic across multiple USB ports, the xHCI controller may fail to service USB 2.0 Isochronous IN endpoints within the required service interval.

Implication: USB 2.0 isochronous devices connected to the xHCI controller may experience dropped packets.

Note: This issue has only been observed in a synthetic environment.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

12. xHCI Link Protocol Field Value

Problem: The xHCI Host Controller reports the Link Protocol (LP) bits [15:14] as 0x0h in the XECP_SUPP_USB3_5 Super Speed Plus register (xHCI MMIO offset 8034h). The xHCI spec rev 1.1 (published in Nov. 2017) defines this bit should be set to 0x1h for SuperSpeed USB 10 Gbps port.

Implication: USB-IF xHCI CV TD 1.9 may report a failure. The failure was not observed during the USB certification for the xHCI USB host controller and thus a waiver was not required.

Note: No functional impact is expected.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.



13. xHCI Short Packet Event Using Non-Event Data TRB

Problem: The xHCI may generate an unexpected short packet event for the last transfer's Transfer Request Block (TRB) when using Non-Event Data TRB with multiples TRBs.

Implication: Transfer may fail due to the packet size error.

Note: This issue has only been observed in an synthetic environment. No known implication has been identified with commercial software.

Workaround: None identified.

Intel recommends software to use Data Event TRBs for short packet completion.

Status: For the steppings affected, refer to the Summary Tables of Changes.

14. eSPI SBLCL Register Bit Not Cleared by PLTRST#

Problem: The IOSF-SB eSPI Link Configuration Lock (SBLCL) bit (offset 4000h, bit 27 in eSPI PCR space) is reset by RSMRST# assertion instead of PLTRST# assertion.

Implication: If the SBLCL bit is set to 1, software will not be able to access the eSPI device Capabilities and Configuration register in the reserved address range (0h - 7FFh) until RSMRST# asserts.

Workaround: None identified.

If software needs to access the eSPI device reserved range 0h - 7FFh while SBLCL bit is set to 1, a RSMRST# assertion should be performed.

Status: For the steppings affected, refer to the Summary Tables of Changes.

15. xHCI Host Controller Reset May Cause a System Hang

Problem: The xHCI host controller may fail to response if either of the two actions are performed:

1. Accessing xHCI configuration space within 1 ms of setting the xHCI HCRST (Host Controller Reset) bit of the USB Command Register (xHC IBAR, offset 80h, Bit[1]), or
2. Setting the HCRST bit two times within 120 ms.

Implication: The system may hang.

Workaround: None identified.

Note: Software must not make any accesses to the xHCI Host Controller registers for 1 ms after setting the HCRST bit 1 of the USB Command Register (xHCI BAR + 80h) and must add a 120 ms delay in between consecutive xHCI host controller resets.

Status: For the steppings affected, refer to the Summary Tables of Changes.

16. xHCI Protocol Speed ID Count Field

Problem: The xHCI Host Controller reports an incorrect protocol Speed ID Count value for the USB 3.2 Supported Protocol Capability register -xHCI MMIO offset 8028 bits [31:28].

Implication: USB-IF xHCI CV TD 1.9 may report a failure.

Note: No Functional impact is expected.

Workaround: None Identified

Status: For the steppings affected, refer to the Summary Tables of Changes.



17. Intel® Serial I/O Controller DMA LLP 4 GB Boundary Alignment

Problem: If software assigns a 4 GB-aligned address to the Linked List Pointer (LLP_LOn = 0h) for Intel® Serial I/O Controller DMA engine, then the DMA engine interprets this as an empty link list and will not perform DMA transfers.

Implication: An Intel® Serial IO controller (i.e. I²C, GSPI, or UART) may stop operating which may cause the system to hang.

Workaround: Driver software should not assign LLP to a 4 GB-aligned address.

Note: This issue has been addressed in the Intel Serial IO drivers in the following versions or later: For Microsoft* Windows* 10, I²C device driver rev 30.100.1724.2, SPI device driver rev 30.100.1725.1, and UART device driver rev 30.100.1725.1.

Status: For the steppings affected, refer to the Summary Tables of Changes.

18. System May Hang with USB-C* Power Adapter

Problem: Connecting a USB-C* power adapter to a PCH USB port may cause a race condition that can result in a xHCI controller hang. This issue only occurs on designs where the USB-C Power Delivery (PD) implements OOB messaging to communicate with the PCH for port mapping.

Implication: The system may hang.

Note: This issue does not occur when the system is in Sx state and has only been observed when repeatedly connecting a USB-C power adapter.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

19. Audio Global Time Synchronization Register Access

Problem: Disabling the audio DSP through the Intel(R) High Definition Audio Function Configuration Register Offset 530h in the PCH Private Configuration Space by setting bit 2 to '1' will block accesses to Audio Global Time Synchronization registers in MMIO space (Offset 500h - 55Fh).

Implication: Audio Global Time Synchronization registers may not be accessible and any attempted accesses may result in a system hang.

Workaround: None identified.

Status: For the steppings affected, refer to the Summary Tables of Changes.

20. Phase Lock Loop (PLL) Feedback Circuit

Problem: The Main PLL and USBPCIe PLL have independent feedback circuits. A feedback circuit timing marginality may result in a momentary jitter excursion in the corresponding PLL and downstream circuitry.

Implication: If the Main PLL loses lock, then the system may hang. If the USBPCIe PLL loses lock, USB 3.1 / SATA / PCIe / integrated GbE / DMI / CLKOUT_PCIE interfaces may experience errors, including correctable errors, interface downtrains, or hangs.

Workaround: A fix has been identified for this erratum and may be available in a software update.


Status: For the steppings affected, refer to the Summary Tables of Changes.





Specification Change

There are no Specification Changes in this revision of the Specification Update.



Specification Clarification

1. **PCIe Precision Time Measurement (PTM) Byte Order**

Added the following note to the Intel® 400 Series Chipset Family On-Package Platform Controller Hub (PCH) Datasheet Volume 1 of 2 (#615170) in the section Precision Time Measurement (PTM):

PCIe Root Ports transmit the lower byte [7:0] of the Propagation Delay Field first instead of the upper byte [31:24] within their PTM DelayResponseD (Response with Data) messages.

2. **SX_EXIT_HOLDOFF# Not Functional with eSPI Enabled**

Added the following note to the Intel® 400 Series Chipset Family On-Package Platform Controller Hub (PCH) Datasheet Volume 1 of 2 (#615170) in the Power Management chapter Signal Description section:

When eSPI is enabled, SX_EXIT_HOLDOFF# functionality is not available, and assertion of the signal will not impact Sx exit flows.

§ §