
Report of Compliance

You have successfully completed the entry of new report.

Report No.:2018069554

<Contact person's information>

<Member's profile>

Member number:338

Company name:Intel K.K.

Address:東京都千代田区丸の内3-1-1 国際ビル5階

<Responsible person>

Department:CPRS

Name:Quincy

E-mail:quincy.davis@intel.com

<Contact person>

Address:address that is shown on the test report Department:CPRS Name:Quincy

Phone:503-696-9027

FAX:n/a

E-mail:quincy.davis@intel.com

<Recipient of Acceptance Notice>

Department:CPRS

E-mail:quincy.davis@intel.con

Applied VCCI Rule:VCCI 32-1

General Name of Equipment:J46885, X722-DA2 Classification of Equipment and classification code:Class A / Classification code W2 Product type (Model No.):J46885, X722-DA2 <Brand(1)> Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded Equipment:

<Brand(2)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded Equipment:

<Brand(3)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded Equipment:

<Brand(4)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded Equipment:

<Brand(5)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded Equipment:

Member number of a test laboratory:564 Element Materials Technology Portland-Evergreen Inc.

Name of the testing laboratory:

<Measurement facility registration number>

1) Radiated EMI measurement below 1GHz facility:

2) Radiated EMI measurement above 1GHz facility:

3) Mains port conducted EMI measurement facility:

4) Wired network port and other port Conducted EMI measurement facility:

5) Article 15 registered laboratory:A-0108

6) This compliance verification test was conducted at the installation site of users.:

Date of testing:2018-08-28

Serial No. of the test report:INTE5898